



**Atlantic County Division of Public Health
Environmental Health Unit
201 South Shore Road
Northfield, NJ 08225
(606) 645-5971**

Hot Tub/Spa Inspection Report

Facility Name Village at English Mill - Hot Tub				Owner Name Tara Frontera - Associa Mid Atlantic, property manager			
Facility Address 1 Village Grande Road				Mailing Address 1 Village Grande RD			
City Egg Harbor Township	State NJ	Zip Code 08234	Phone	City Egg Harbor Twp	State NJ	Zip Code 08234	Phone (609) 788-8405
Name of Inspecting officer Allen Benowitz			Title Senior R.E.H.S.		REHS Lic Number B-2033	Name of Health Officer	
Record Number: PR0002785	Risk	Municipality 28 Egg Harbor Township		Date 03/17/2025	Start 10:20 AM	Finish 10:40 AM	
Program Code: 0204 Hot Tubs - Indoor		Program Identifier Village at English Mill - Hot Tub		Purpose of Inspection: Hot Tub Inspection		Evaluation Satisfactory	

Fill in the designated compliance status (IN OUT N/O, N/A) for each each numbered item Fill in the appropriate box for COS and/or R
 IN = In compliance OUT = Not in compliance N/O = Not observed N/A = Not applicable COS = Corrected on-site during inspection R = Repeat violation


APPROVALS		
1. Checklist submitted and approval issued		In
PERSONNEL CERTIFICATIONS		
2. Individual currently certified in First Aid/CPR readily accessible		N/A
3. Designated Adult Supervisor		In
4. Trained Pool Operator certification current/documented visit once per week		In
WATER QUALITY		
5. Log book maintained		In
6. Complete test kit w/ readable comparator		In
7. Bromine level within acceptable range		In
8. Free chlorine level within acceptable range		N/A
9. Combined chlorine level within acceptable range		N/A
10. Ph within acceptable range		In
11. Water clarity acceptable / algea free		In
12. Water tested weekly by certified lab		In
MAIN DRAIN(S)		
13. Covers are intact & properly secured		In
14. Covers comply with VGB Act		In
15. 2 or more main drains at least 3 ft apart and connected to one pump		In
16. Single main drain secondary backup system installed and accessible		N/A
17. Emergency pump shut-off switch is prominently marked		In
HEATER & TEMPERATURE REQUIREMENTS		
18. Visible thermometer located at hot tub. Water temperature at time of inspection is <104 degrees F		In
19. Automatic safety shut-off to heater is in working order		In

SAFETY FEATURES & MAINTENANCE	
20. Clock is located next to hot tub	In
21. Complete first aid kit	In
22. Minimum of 2 depth markings within 18" of water's edge & are legible to a person standing on the deck facing the water	In
23. Fences & gates are in good repair	In
24. Locks provided at entrances	In
25. Skimmers are clean & free of excess debris	In
26. Deck area is clean & in good repair	In
27. Bathroom is clean, toilet tissue, soap & paper towels provided	In
28. Backwash is disposed of properly	In
SIGNAGE (CONSPICUOUSLY POSTED)	
29. Sign conspicuously posted indicating location & method of access of FA/CPR personnel if not stationed at hot tub or spa	In
30. Bathers rules posted (11 rules)	In
31. Precautionary sign posted (6 rules)	In
32. "No Smoking" sign posted at chemical storage area	In

VIOLATIONS, OBSERVATIONS AND CORRECTIVE ACTIONS

Item No	Remarks
7	Bromine 6.0
10	PH 7.4
12	Precision analytical

Overall Inspection Comments:
 NJ State Recreational Bathing Code inspection revealed:
 This is the first 2025 pool code inspection for this indoor hot tub.
 Frank Canale, Canale Pools, is TPO.
 Frank Canale was PIC for inspection. Frank Canale Canale Pools, signed the report emails to send inspection reports canalepools@gmail.com and Tara.frontera@associamidatlantic.com
 Precision Analytical/ York conducts weekly bacteria testing.
 hot tub temperature at time of the inspection was 98°F. The hi temp box located next to spa was also reading 99°F and was working properly to alarm at set point.
 chemical readings
 free bromine 6.0
 ph 7.4
 Rating Satisfactory

Received By: Frank Canale		Title:	Date: 03/17/2025
-------------------------------------	---	---------------	----------------------------

Facility Name:
Village at English Mill - Hot Tub

Date:
03/17/2025

Page 3 of 3

Inspector:
Allen Benowitz



Title:
Senior R.E.H.S.

Date:
03/17/2025